

ThermoFisher SCIENTIFIC

THERMOFISHER DIAGNOSTICS LTD.
RUNCORN, CHESHIRE, WA71TA
RUNCORN

Service Report

DATE: 01/03/2016

TO:	FOR:
Hazel Smith Q2 Solutions AP Department 01506816080	Work Order Number#: WO-00003186 Case Number#: 00002753 Location Info: Alba Campus Livingston, LOTHIAN, EH54 7EG

WORK ORDER DETAILS			
Installed Product	10039691 - APB35600001	Order Type	Installation
Serial Number	H9909153248 :	System Billing Type	Billable
Product	TISSUEWAVE II 220-240V	Symptom	Other
PROBLEM DESCRIPTION			
Visit required following email to Sheila Dandy			
WORK PERFORMED			
Instal rear vent pack to customer extraction system. carry out power output test using external digital thermometer. EC test < 1 ohm@500V DC IR test >> 2 Megohms . Power output calculated at 805 watts at 100% output. All measurements are within spec and all serviceability checks carried out.			

PARTS USED

Part	Line Qty
Total	0

PARTS REMOVED

Part	Line Qty
Total	0

LABOR DETAILS

Activity Type	Material Code	Line Qty
Labor	SDG Service Labor - Standard	5
Total		5.0000

TRAVEL

Activity Type	Material Code	Line Qty
Travel	Actual Travel APD	4
Total		0.000

OTHER EXPENSES

Expense Type	Material Code	Line Qty
Total		0

Customer Signature:

[Handwritten Signature]

Technician:

[Handwritten Signature]