

INVOICE STATEMENT FORM

	605 COLE	BY DR	UVE, V	MATERI			
				WAILILL	00, ON N2V	/ 1A1	
Date:JULY	20, 2022		Iı	nvoice No:			
	HENDERSON BRE			MPANY IN	NC		
	28 A STERLING I						~
	TORONTO, ONTA	RIO N	16R 2	B7			
Reported to:	STEVE HIMEL		P	.O. # 20)22-CENT	Jol	o# SO#22-1535
Locations Worked	d: WATERLOO	SHO	– P/ PLA	NT _		-	
Dates Worked:	MAY 6, 2022	ТО Л	ULY 4	, 2022			
4.0	Reg. Hrs. Shop	<u>@</u>	\$	160.00	per Hr.	\$	640.00
9.5	Reg. Hours Plant	<u>@</u>	\$	160.00	per Hr.	\$	1,520.00
	OT hours Plant	<u>@</u>	\$	200.00	per Day	\$	-
12.0	Reg. Hrs. Travel	<u>@</u>	\$	95.00	per Hr.	\$	1,140.00
	OT Hrs. Travel	<u>@</u>	\$	100.00	per Hr.	\$	-
3	_ Days Meals	<u>@</u>			per Day	\$	168.11
666	_Kilometers	<u>@</u>	\$	0.95	per km	\$	632.70
	_Vehicle Rental	<u>@</u>			per Day	\$	-
	Accommodations	<u>@</u>			per Day	\$	-
9.5	_2nd Man	<u>@</u>	\$	110.00	per Hr.	\$	1,045.00
					Airfare	\$	-
			C	ab Fare and	d/or Parking .	\$	-
Misc. Expenses _	EMERGENCY S	ERVI	CE TC	VNPX 50	07		
Misc. Expenses _	AND SHOP REP	AIR					
Misc. Expenses	CLEAN TAPERI	ED BC	RE IN	BOWL E	BOTTOM	\$	761.33
Parts- Onsite	SEE ATTACHEI	D LIST	ΓING			\$	1,772.55
Parts - shop	SEE ATTACHEI	D LIST	TING			\$	14,201.96
inedunos adalestos	2	T	OTAL	OF THIS I	INVOICE	\$	21,881.65

applicable taxes extra

SEE REPORT FOR DETAILS ON SERVICE



FIELD SERVICE REPORT

JOB NO: CUSTOMER: MACHINE:	SO#22-1535 HENDERSON BE SERIAL NO. BOWL TYPE PRODUCT	REWING COM ALFA LAVAL 4179970 CLARIFIER BEER		SGD-31	- - - -	
MACHINE CONDITION:		Р	F	G	E	*
	INLET - OUTLET			х		
	PUMP ASSEMBLY			х		
	BOWL		х			
	WATER CONTROL			х		
	FRAME			х		
ACTION TAKEN:			Υ	N		
	INLET - OUTLET		х			
	PUMP ASSEMBLY		х			
	BOWL		х			

X

X

WATER CONTROL

FRAME

^{*}see attached page for comments



Date: May 6, 2022

CALL FROM PLANT - PROBLEMS WITH ALFA LAVAL VNPX 507

START TIME

ARRIVED AT:

8:30 A.M.

MACHINE LOCKED OUT

YES

INLET-OUTLET:

DISMANTLE, CLEAN.

COMMENTS--

IN GOOD SHAPE CARBON SEALS SEEM TO HAVE WORN

OVERTIME BUT NOT DETRAMENTAL TO OPERATION.

PUMP ASSEMBLY:

DISMANTLE, CLEAN AND RESEAL

COMMENTS--

BOWL WAS VIBRATING AT TOP SPEED THE PUMPS LOOSENED AND CAUSED DAMAGE TO BOWL TOP AND THE BOTTOM OF PUMPS. BROUGHT PUMPS BACK TO SHOP TO CLEAN UP.

BOWL ASSEMBLY

DISMANTLE, CLEAN AND RESEAL

BOWL HEIGHT MEASURED AT:

19MM

COMMENTS--

BOWL WAS CLEAN. DID NOT TOUCH BOWL AT THIS TIME.

FRAME

COMMENTS--

WATER LEAKED INTO OIL DUE TO SEAL FAILURE. THIS CAUSED

BEARINGS TO FAIL AND HIGH VIBRATION IN MACHINE.

Work time: 3 hrs; Travel: 4 hrs; Mileage: 222 kms



Date: May 9, 2022

START TIME

ARRIVED AT:

12:30 P.M

MACHINE LOCKED OUT

YES

**ARRIVED ON SITE TO REINSTALL SPINDLE.
WE DID A MINOR SERVICE ON BOWL CHANGING ALL SEALS AND GASKETS.
AFTER FURTHER INSPECTION THE BOWL NAVE WAS DAMAGED AND HAD
BEEN SPINNING ON SPINDLE. HAD TO REMOVE BOWL AS IT DID NOT
FIT ON SPINDLE ANYMORE. BROUGHT BOWL AND SPINDLE BACK TO
SHOP FOR MACHINING AND TO MAKE NEW FITS.

Work time: 3.5 hrs; Travel: 4 hrs; Mileage: 222 kms

Date: July 4, 2022

START TIME

ARRIVED AT:

10.30 A M

MACHINE LOCKED OUT

YES

**RETURNED WITH NEW SPINDLE WITN NEW BEARINGS INSTALLED.
BOWL WAS MACHINED TO FIT NEW SPINDLE TO ENSURE BEST FIT.
DID FULL INSPECTION AND INSTALLED SPINDLE WITH NEW OIL
IN FRAME. INSTALLED BOWL AND ENSURED THAT IT FIT CORRECTLY
WITH SPINDLE NUT. NO ISSUES WERE DETECTED AND WENT AHEAD
AND INSTALLED MACHINE FULLY ALONG WITH NEW CARBON SEALS.
RAN MACHINE FOR ONE HOUR ON WATER TESTING WITH OPERTATOR.
SHOOTS WELL AND CLOSES WELL. MACHINE RUNS SMOOTH WITH
PERFECT OPERATION.




MACHINE ASSEMBLY:

COMPLETED AT:	1:00 P.M.
a) RAMP UP TIME	8 MINUTES
b) VIBRATION	2.1 MM/S
c) FILLED BOWL AND C	OMPLETED MANUAL DESLUDGE
	YES
d) MOTOR AMPS ON ST	TART: 8
MOTOR AMPS NO LO	DAD: 6
MOTOR AMPS DESL	UDGE: 11

Work time: 3 hrs; Travel: 4 hrs; Mileage: 222 kms

DATE: JULY 6, 2022

TECHNICIANS: ERROL SINGH, ADAM ZID & CEDRIC SARRASY



FIELD REPAIR PARTS

JOB NO. SO#22-1535/ SO#22-1126

MACHINE NO ALFA LAVAL VNPX 507

CUSTOMER HENDERSON BREWING COMPANY INC

LOCATION TORONTO, ONTARIO

QTY	PART NUMBER	DESCRIPTION	PRICE EACH	TOTAL
Frame:				
1	CUA223406-27	O RING	\$4.36	\$4.36
1	CUA223406-27	O RING	\$4.36	\$4.36
1	CUA542392-02	SEAL RING	\$23.18	\$23.18
Machine Top	:			
1	CUA223412-45	O RING	\$26.96	\$26.96
1	CUA223412-29	O RING	\$8.10	\$8.10
1	CUA260168-36	O RING	\$2.35	\$2.35
1	CUA260190-05	O RING	\$50.40	\$50.40
1	CUA223406-43	O RING	\$4.20	\$4.20
1	CUA223406-43	O RING	\$4.20	\$4.20
Inlet / Outlet:				
1	CUA564044-42G	O RING	\$3.93	\$3.93
1	CUA223406-16	O RING	\$1.00	\$1.00
1	CUA223406-16	O RING	\$1.00	\$1.00
1	CUA567772-03G	O RING	\$56.77	\$56.77
Drive:			·	
1	CUA260169-49	FLAT BELT	\$216.34	\$216.34
Bowl:				, , , , , ,
1	CUA2234121-40	O RING	\$3.65	\$3.65
1	CUA547963-07	RECTANGULAR RING	\$49.16	\$49.16
1	CUA223412-15	O RING	\$10.05	\$10.05
1	CUA223412-30	O RING	\$5.05	\$5.05
1	CUA547963-08	RECTANGULAR RING	\$51.06	\$51.06
3	CUA547993-01	VALVE PLUG	\$6.75	\$20.25
1	CUA547963-06	RECTANGULAR RING	\$18.15	\$18.15
1	CUA223412-48	O RING	\$11.70	\$11.70
1	CUA223412-30	O RING	\$5.05	\$5.05
1	CUA546198-25	O RING	\$5.85	\$5.85

QTY	PART NUMBER	DESCRIPTION	PRICE EACH	TOTAL
Bowl Cont:	- P.			
1	CUA547963-05	RECTANGULAR RING	\$127.21	\$127.21
1	CUA223406-14	O RING	\$3.33	\$3.33
1	CUA223406-40	O RING	\$4.65	
1	CUA547728-01	SEAL RING	\$188.73	\$188.73
1	CUA546198-15	O RING	\$11.23	\$11.23
1	CUA223412-30	O RING	\$5.05	
1	CUA567772-02G	O RING	\$67.23	\$67.23
1	CUA567772-01G	O RING	\$67.42	\$67.42
Machine Bott	tom:			7
2	CUA9876	BEARING	\$325.96	\$651.92
8	CUA223406-20	O RING	\$1.96	\$15.68
1	CUA223412-45	O RING	\$26.96	\$26.96
1	CUA223402-24G	O RING	\$3.04	\$3.04
1	CUA223406-26	O RING	\$1.26	\$1.26
1	CUA223406-20	O RING	\$1.96	\$1.96
Miscellaneous:			·	
1	ONTC100	PETRO GEL	\$9.76	\$9.76
			TOTAL	\$1,772.55

Done by: LOUISE BROWN Date: JULY 7, 2022



SHOP SERVICE REPORT

JOB NO:

SO#22-1535/WO#22-1126

CUSTOMER: HENDERSON BREWING COMPANY INC

MACHINE:

ALFA LAVAL VNPX 507 SGD-31

SERIAL NO.

4179970

BOWL TYPE CLARIFIER

PRODUCT BEER

COMMENTS: SHOP REPAIR

Date: May 9/22

* INSPECT NEW SPINDLE AND TEST FIT INTO BOWL NAVE FIT


* REBUILD VERTICAL ASSEMBLY

* CHANGE CARBON SEALS

* CLEAN BOWL BOTTOM

shop time: 4hrs

TECHNICIAN: ADAM ZID



SHOP REPAIR PARTS

JOB NO.

SO#22-1535/ SO#22-1126

MACHINE NO ALFA LAVAL VNPX 507

CUSTOMER HENDERSON BREWING COMPANY INC

LOCATION

TORONTO, ONTARIO

QTY	PART NUMBER	DESCRIPTION	PRICE EACH	TOTAL
1	CUA547831-01G	BOWL SPINDLE	\$8,195.07	\$8,195.07
1	CUA567756-01G	SEAL RING	\$2,530.21	\$2,530.21
1	CUA567772-01G	O RING	\$71.26	\$71.26
1	CUA567772-02G	O RING	\$71.47	\$71.47
1	CUA567772-03G	O RING	56.77	\$56.77
1	CUA567773-01G	STATIC SEAL	\$3,142.78	\$3,142.78
1	ONTC103	GEAR OIL EP220	\$134.40	\$134.40
			TOTAL	\$14,201.96

Done by:

LOUISE BROWN

Date: JULY 7, 2022